

## **SAS Superstructure**

Location: 04-SF-80-13.2 / 13.9 Client Name: CalTrans

Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Diary #: 885 Const Calendar Day: Saturday 418 Date: 27-Jul-2013 Inspector Name: Bruce, Matt Title: Transportation Engineer

Continuous Inspection Type:

Shift Hours: 07:00 am 05:30 pm **Break:** 00:30 Over Time: 10:00

Federal ID: Location:

Reviewer: Status: Submit Wilcox, Jason Approved Date:

Weather

Temperature 7 AM 50 - 60 **12 PM** 60 - 70 **4PM** 60 - 70

Precipitation 0.00" Condition Partly cloudy

Working Day | If no, explain:

Dispute Diary:

### Work description.

- See Pamela Gagnier's diary for the S1/S2 Shear Key modification work today as she is tracking the labor, equipment, and work progress of Conco and Harris Salinas personnel. Brian Wolcott is responsible for ABFJV personnel at Pier 7.
- Took measurements of the S2 Shear Key retrofit Vertical, Draped, Bottom Longitudinal, and Bottom Transverse tendon blockouts. Bearing plate angles, horizontal distances for working points, horizontal angles off the forms were measured for all bearing plate/styrofoam blockouts. There was a considerable amount of Vertical tendon blockouts which will need to be adjusted in the transverse direction for the "A" row (0.0 degrees) and the "B" row (3.0 degrees towards the saddles/concrete).

CCO-327	Bid Item: 001	0-FIS-ELS.327	Pier E2 Fa	lsework	/Install S	Saddle		
AMERICAN BRII	OGE/FLUOR, A JV							
Labor								
Trade	Class	Name	RT Hrs	OT Hrs	DT Hrs	Total	Remarks	Dispute
Contractor: AMERICAN BRIDGE/FLUOR, A JV								
Operator	JNM	RICHARD TAYLOR	0.00	10.00	0.00	10.00		
Ironworker	APP	JAMES MIRANDA	0.00	10.00	0.00	10.00		
Ironworker	JNM	RENE ESQUIVEL	0.00	10.00	0.00	10.00		
Ironworker	APP	ETHAN KENT	0.00	10.00	0.00	10.00		
Ironworker	FOR	JAMES BENNINGHOVE	0.00	10.00	0.00	10.00		
- Provided support with the Terex RT160 crane and shipping materials from Pier 7 on a barge to the E2								
Work description. 001 0-FIS-			-ELS.327					
Pier. I am c	overing ABF ope	erations today at the l	E2 cap be	am and	o not a	t PIP		
	- f fb - O4 Ob -	/  -     4	•				•	
side section		•	he side pla	ates. A	lso pla	ced/bo	olted the side plates for the	
side section S2 Shear K	ey retrofit. See F	amela Gagniers diar	he side pla y for any a	ates. A additio	lso pla nal con	ced/bo	•	
side section S2 Shear K	ey retrofit. See F	•	he side pla y for any a	ates. A additio	lso pla nal con	ced/bo	olted the side plates for the	
side section S2 Shear K inspect this	ey retrofit. See F	amela Gagniers diar	he side pla y for any a	ates. A addition equipr	lso pla nal con nent.	ced/bo	olted the side plates for the	
side section S2 Shear K inspect this	ey retrofit. See F work, even thou Bid Item: 001	Pamela Gagniers diar gh I am covering the	he side plant by for any a labor and	ates. A addition equipr	lso pla nal con nent.	ced/bo	olted the side plates for the	
side section S2 Shear K inspect this CCO-330 SCHWAGER DA	ey retrofit. See F work, even thou Bid Item: 001	Pamela Gagniers diar gh I am covering the	he side plant by for any a labor and	ates. A addition equipr	lso pla nal con nent.	ced/bo	olted the side plates for the	
side section S2 Shear K inspect this CCO-330 SCHWAGER DA	ey retrofit. See F work, even thou Bid Item: 001	Pamela Gagniers diar gh I am covering the	he side pla ry for any a labor and Pier E2 Po	ates. A addition equipr	lso pla nal con ment. ioning	ced/bo	olted the side plates for the	Dispute
side section S2 Shear K inspect this CCO-330 SCHWAGER DA Labor	ey retrofit. See F work, even thou Bid Item: 001	Pamela Gagniers diar gh I am covering the 0-PTS-ELS.330	he side pla ry for any a labor and Pier E2 Po	ates. A addition equiprost Tens	lso pla nal con ment. ioning	ced/bo	olted the side plates for the s as she watched/wanted to	Dispute

Run date 22-Nov-14

7:36 AM

Time

04-0120F4

04-SF-80-13.2/13.9

Self-Anchored

Suspension Bridge

# Daily Diary Report by Bid Item

Job Name: 04-0120F4 Inspector Name Bruce, Matt Diary #: 885 Date: 27-Jul-2013 Saturday

Diary:

Work description. 001 0-PTS-ELS.330

- Completed installing the flexi-duct (portion embedded in concrete w/stickout) for the draped tendons DL1-4 on the West side of the S1 Shear Key retrofit. Placed the East/West BL1 tendons and all of the Vertical PT tendon ducts for the S1 Shear Key retrofit. It should be noted that a plastic shrink wrap was used to seal the connection between the trumpet and pipe or flexi-duct in addition to tape. See photos below for more details of this work.

#### Attachment




Vertical PT tendon duct placement on the East side of the S1 Shear Key retrofit.



Bolt lot can with Loctite compund used for installing the plates and wedge shapes to snug tight.



Wedged sections of the S1 Shear Key retrofit installed today on the East side of the lower stub section.



Plastic shrink wrap used to seal the extra strong pipe of the BL2 tendon seen in the Southwest corner of the S1 Shear Key retrofit.



# Daily Diary Report by Bid Item

Job Name: 04-0120F4 Inspector Name Bruce, Matt Diary #: 885 Date: 27-Jul-2013 Saturday



North side plate and Northeast wedge shaped section for the PT strand saddles.



Length of the bolts used to attach the side plates of the S1 Shear Key.